NOvA Experiment Status All Experimenter's Meeting

Jaroslav Zalesak, Institute of Physics, Prague/FNAL

May 17, 2015

Operations - Summary



□ BEAM:

• Slip stacking 2+6 continues with higher intensity (>400 kW).

□ NearDet:


• Running well. Made tests with powering down HV and study of effects on noisiness of some channels.

☐ <u>FarDet:</u>

- Unplanned beam shutdown used to study DAQ behavior in dependence how many buffer nodes and/or dcms are used in.
- Frequency of the short DAQ downtimes less, the mysterious one dismissed at all.
- After the week deadline we faced the thunderstorm knocked out FarDet and the recovery took more 12h with many issues.
- □ <u>Control Room(s)</u>: We used only 1 shifter on duty even if in one of the remote control rooms.

FD: Data taking Uptime






- Last week running uptime efficiency was only 90.0%, in total of 17 hours down.
- ➤ Most of them (13h) when beam down and other 2 hours during low beam intensity.
- ➤ Beam lost only during 2 hours (excluding the power glitch last night).
- Number of short DAQ crashes significantly went down comparing a week ago.

Jaroslav Zalesak - AEM 5/18/2015

FD: POTs delivered/recorded





- ➤ Past week efficiency was good comparing last weeks at 97.9%, (7.51 of 7.68 e18 POTs).
- ➤ The absolute values were low due to 2+ day beam absence.

The power glitch beam lost are not seen in this picture.

Jaroslav Zalesak - AEM 5/18/2015

FD: Accumulated POTs



5



> 2013/14: 280/326 e18 POTs (86%) + 2014/15: 238.3/248.7 e18 POTs (95.8%) [205 days]

Jaroslav Zalesak - AEM 5/18/2015

Power glitch at Ash River site



☐ <u>FarDet:</u>

- After the week deadline we faced the thunderstorm caused short (in seconds) power outage affected both detector PS and computers.
- Resulted to significant data taking down time, estimated for 15.5 hours, starting Sunday (5/17) evening at about 18:37.
- Power outage recovery usually takes 2-4 hours, depending on the issues encountered with the large DAQ and Detector Controls computing cluster, the custom timing and readout hardware, and the cooling of APDs.
- In this case, the recovery has been prolonged due to the interaction of various technical and procedural issues, predominantly with our timing system.
- The timing system is fully recovered, and we are taking data since 10:30 (after 1 hour running a break needed for the DSO/pedestal scan).